Failure analysis and optimization of coil spring fracture in MacPherson suspension system

Xiang Li^{1,2,*}, Xiaowen Zhu^{1,2}, Gang Xu¹, Xiaoqiang Cheng²

¹College of Automotive Studies, Tongji University, Shanghai, 200092, China ²Jiangling Motors Corporation, Ltd., Nanchang, 330001, China

* Xli61@jmc.com.cn

Abstract. During a vehicle accelerated corrosion test, a front coil spring in the MacPherson suspension system of an SUV exhibited fracture failure. The results indicated that the material composition, microstructure, and decarburization layer of the coil spring met the technical requirements; however, the tempering hardness was found to be excessively high. Fracture surface analysis revealed a small amount of intergranular cracking in the crack initiation zone, and the crack propagation zone exhibited ductile tearing characteristics, ultimately leading to fatigue fracture. Through force analysis, it was determined that the coil spring was subjected to lateral loads. Additionally, ABAQUS software simulations revealed that during wheel hop conditions, the coil spring end coil came into contact with the spring seat, leading to coating failure and the formation of surface fatigue defects. Based on these findings, an improvement plan was proposed, followed by failure reproduction and optimization validation in a test rig.

Keywords: coil spring, failure analysis, fatigue fracture, test verification

1. Introduction

The MacPherson suspension system typically consists of a shock absorber, coil spring, stabilizer bar, lower control arm, and steering knuckle. Due to its high space utilization, excellent handling performance, and effective shock absorption, it is widely used in the front-wheel suspension of automobiles. As an elastic component, the coil spring plays a crucial role in supporting the vehicle's weight and absorbing road impacts. During operation, the spring undergoes repeated compression and rebound, enduring cyclic alternating loads, with fatigue fracture being the most common failure mode [1-2].

In a full-vehicle accelerated corrosion test conducted by an automotive company, the front coil spring fractured at approximately 0.8 turns from the lower end after 57 test cycles, as shown in Figure 1. However, this coil spring had successfully passed the vehicle structural durability test and a 200,000-cycle test at frequencies of 1-6 Hz on a test rig without failure, meeting the required fatigue life standards. To investigate the cause of the failure during the corrosion test, a comprehensive failure analysis was performed, including chemical composition assessment, hardness testing, macro and micro fracture morphology examination, metallographic structure evaluation, and shot peening process inspection.



Figure 1. Fractured Coil Spring

2. Coil spring manufacturing process

The coil spring is made of alloy spring steel 55CrSi, with a wire diameter of Φ 13.4 mm. The manufacturing process involves cold coiling, tempering, hot pre-setting, shot peening, cold pre-setting, pre-treatment, and powder coating. The required microstructure is tempered troostite, with a hardness specification of 52-56 HRC, and the decarburization layer depth must not exceed 1% of the wire diameter.

3. Failure cause analysis

3.1. Chemical composition inspection

The chemical composition analysis of the failed coil spring confirmed that it met the technical specifications for 55CrSi material, as shown in Table 1.

Element	С	Si	Mn	Cr	Р	S
Technical Requirement	0.5~0.6	1.2~1.6	0.5~0.8	0.5~0.8	≤0.03	≤0.03
Measured	0.53	1.35	0.72	0.69	0.07	0.01

Table 1. Chemical Composition Analysis of the Front Coil Spring (Mass Fraction, %)

3.2. Surface hardness inspection

The coil spring in question was manufactured using a cold coiling process, and its hardness was tested using a Rockwell hardness tester (HR-150A) on a cross-section taken from the fracture surface. The measured hardness values were HRC 54.2, 54.7, 56.3, 57.0, 54.6, 55.9, 57.5, 55.3, 57.4, 54.8, with an average hardness of HRC 55.8. Some localized areas of the cross-section reached HRC 57 or above, indicating excessive hardness.

3.3. Metallographic examination

A sample from the fracture surface was cut and polished following the ASTM E 3-01 standard for metallographic analysis. The microstructure was confirmed to be tempered troostite, which met the required metallurgical specifications, as shown in Figure 2.



Figure 2. Metallographic Structure (500×)

The decarburization layer depth was measured according to the JIS G0558 standard for steel decarburization measurement. The results confirmed that there was no surface decarburization, as shown in Figure 3.



Figure 3. Surface Decarburization Depth (100×)

3.4. Shot peening residual stress analysis

Shot peening is a common surface treatment process used to enhance the mechanical properties of metal materials. This process involves high-pressure air propelling steel shot at the metal surface to induce plastic deformation and introduce a compressive residual stress layer, which helps counteract tensile stresses caused by external loads. This is particularly beneficial for improving fatigue resistance under cyclic loading, such as that experienced by automotive coil springs [3].

After removing the surface coating, the X-ray diffraction method was used to measure the residual stress of the coil spring. Measurements were taken from the surface to a depth of 0.3 mm, with increments of 0.05 mm, as shown in Figure 4. The surface compressive residual stress was measured at 667 MPa, with the maximum residual stress observed at 104 µm below the surface. The shot peening stress distribution was within the normal range.



Figure 4. Residual Stress vs. Depth Results

3.5. Fracture surface analysis

3.5.1. Macroscopic examination

The coil spring fractured at 180° along the contact surface between the first coil and the lower spring seat. In this region, the coating had peeled off, and severe corrosion and rust formation were observed. As shown in Figure 5, the failure zone was divided into three distinct regions: Region A (Contact Area with the Spring Seat): Exhibited a metallic luster, indicating long-term dynamic wear at the contact interface. Region B (Crack Propagation Zone): Displayed reddish-brown rust, which spread radially along the wire diameter due to corrosion testing. The propagation direction suggested that the fatigue crack originated from the lower surface of the coil spring. Region C (Final Fracture Zone): Located at the inner and outer sides of the spring coil, this area was shiny and smooth, characteristic of an instantaneous overload fracture. Based on these observations, the primary failure mechanism was identified as stress corrosion fatigue fracture caused by coating damage.



Figure 5. Macroscopic Image of the Fractured Coil Spring

3.5.2. Microscopic fracture analysis

The fracture surface was cleaned to remove rust, and a ZEISS Sigma300 field emission scanning electron microscope (SEM) was used for microscopic analysis:

(1) Crack Initiation Zone: Due to severe rusting, the precise morphology of the crack origin was not clearly visible (Figure 6).



Figure 6. Crack Initiation Zone

(2) Initial Crack Zone: A small amount of intergranular cracking was observed, as indicated by the arrows in Figure 7. This was identified as the original fatigue crack initiation site.



Figure 7. Initial Crack Zone

(3) Crack Propagation Zone: Exhibited ductile dimple features, as shown in Figure 8, indicating that the crack propagation was accompanied by localized plastic deformation. This high-strain zone confirmed that the fracture mechanism was fatigue failure.



Figure 8. Dimple Features in the Crack Propagation Zone

3.5.3. EDS spectrum analysis

Energy-dispersive spectroscopy (EDS) was performed on the crack initiation area. Spectral analysis of points A and B, as shown in Figure 9, revealed that the primary component was iron oxide (Fe₂O₃). Additionally, the presence of Mg, K, Ca, and Cl elements suggested contamination from multi-component salts commonly used in corrosion testing.



(a) Crack Source Area (b) Spectrum A (c) Spectrum B

Figure 9. EDS Analysis Results

In summary, microscopic analysis revealed the presence of intergranular cracking at the crack initiation site, indicating that during the vehicle accelerated corrosion test, wear between the spring and the damper seat led to coating damage [6]. This exposed the spring to saltwater corrosion, which penetrated the grain boundaries, weakening the intergranular bonding and forming crack initiation sites [5]. Under cyclic loading, these cracks continued to propagate, eventually resulting in fatigue fracture.

4. Force analysis and design optimization of coil spring

4.1. Force analysis

Figure 10 illustrates the force analysis of the MacPherson suspension system, which can be simplified into three forces: W, F_C and FA. FA represents the constraint force exerted by the vehicle body on the upper mount of the damper. W is the reaction force from the ground acting on the tire (excluding the unsprung mass). $F_{\rm C}$ is the constraint force from the lower control arm. Based on the planar force equilibrium theory, the magnitude and direction of F_A can be calculated using W and F_C , as shown in Figure 10(b). F_A can be further decomposed into: F_{Ay} : the force along the spring's axis. F_{Ax} : the force perpendicular to the shock absorber's axis, as shown in Figure 10(c).



Figure 10. Force Analysis of the MacPherson Suspension Strut

The force F_{Ax} represents the lateral force acting on the shock absorber assembly, which can be further distributed among the lateral forces on the piston rod, acting at the seal and piston, and the lateral force on the coil spring (F_{lat}).

Under static conditions, using the known external force F_{lat} and the spring's lateral stiffness K_{lat} , the relative displacement between the spring and the spring seat can be estimated using Hooke's Law, as shown in Equations (1) and (2).

$$\Delta x = \frac{F_{lat}}{K_{lat}} \tag{1}$$

$$K_{lat} = \frac{R\xi}{\xi - 1 + \frac{1}{\frac{1}{2} + \frac{C}{E}} \sqrt{\left(\frac{1}{2} + \frac{G}{E}\right) \left(\frac{G}{E} + \frac{1 - \xi}{\xi}\right) \tan\left[\lambda\xi\sqrt{\left(\frac{1}{2} + \frac{G}{E}\right) \left(\frac{G}{E} + \frac{1 - \xi}{\xi}\right)}\right]}}$$
(2)

Where:

 $\xi = \frac{S}{H_0}$ represents the vertical compression ratio of the spring. $\lambda = \frac{H_0}{D}$ represents the slenderness ratio of the spring.

Ho is the free height of the spring.

S is the vertical deformation of the spring.

D is the mean coil diameter of the spring.

E is the elastic modulus of the spring material.

G is the shear modulus of the spring material.

4.2. CAE simulation of spring end coil under wheel hop conditions

As the coil spring deforms under varying loads, its helix shape shifts, causing relative motion between the spring and the spring seat. To analyze this behavior, a CAE simulation was conducted using HyperMesh software with an ABAQUS solver. Under fullload conditions, a 3.5G vertical wheel-hop load was applied at the wheel center and tire contact point. The CAE simulation results indicated that at extreme compression, the lower end coil of the spring exhibited potential for dynamic contact and wear against the spring seat [6], as shown in Figure 11.



Figure 11. CAE Simulation Results of Spring End Coil Contact

In conclusion, due to lateral load effects, there exists slight relative displacement between the coil spring and the damper spring seat. During wheel hop conditions, the spring compression and rebound induce coil twisting deformation, leading to friction with the spring seat. Additionally, in wheel center hop conditions, the lower end coil dynamically contacts the spring seat, exacerbating potential wear. To mitigate lateral forces on the damper, the MacPherson coil spring in this study adopted: Variable diameter and tapered cross-section design for the spring. Angled support surfaces for the spring seat. Given these observations, the recommended solutions include: Enhancing coating wear resistance. Incorporating rubber pads or protective sleeves.

4.3. Design optimization

The coil spring coating process utilizes electrostatic powder spraying, where the powder is uniformly adsorbed onto the spring surface via electrostatic forces, followed by a curing process.

The designed coating thickness is 60–80 µm.

Solution 1: Adjust the tempering hardness from 52–56 HRC to 52–55 HRC. Increase the coating thickness on the end coil from $60-80 \mu m$ to $80-100 \mu m$.

Solution 2: Add a rubber protective sleeve on the spring end coil (or alternatively, place a rubber pad on the lower spring seat). The sleeve would cover approximately 270° of the end coil to prevent direct hard-contact wear.

Solution 3: Implement a dual-layer powder coating: Inner layer: Metal powder-based coating. Total coating thickness: 150-200 µm.



Figure 12. Proposed Design Optimization Solutions

5. Failure reproduction and validation

To validate the optimization proposals outlined in Section 3.3, two sample sets were manufactured for each proposed solution, along with an additional control group using the original design. The samples were subjected to the following tests for comparative analysis, as summarized in Table 2:

Coating wear test: Conducted using a 1/4 vehicle suspension setup, with cyclic loading in the 1-6 Hz range. The test was stopped when the coating damage on the lower end coil exceeded 3 mm.

Salt spray test: Performed according to ASTM B117, with a 20-cycle exposure.

Cyclic fatigue test: Conducted under dry conditions until the spring completed 500,000 cycles or fractured.

Findings from the Tests:

The original design failed to meet the 500,000-cycle fatigue requirement when exposed to intermediate salt spray testing. The fracture occurred at 160° on the lower end coil, with a failure location and mode consistent with full-vehicle corrosion testing. This validated the feasibility of using bench testing for component development and verification.

Effects of design modifications:

Reducing the surface tempering hardness moderately extended the spring's service life.

Dual-layer powder coating improved coating wear resistance, but localized peeling led to eventual coating failure and substrate corrosion.

Rubber protective sleeves helped mitigate dynamic wear between the coil and the spring seat, but had drawbacks:

Water accumulation within the sleeve could cause corrosion. Debris entrapment between the sleeve and the spring could accelerate coating wear. Enclosed sleeves posed the highest corrosion risk. Open, C-shaped, or perforated sleeves were recommended for better drainage and ventilation.

6. Conclusion

This study analyzed the failure mode of the front coil spring in a full-vehicle corrosion test, covering material properties, hardness, residual stress, microstructure, EDS analysis, and fracture surface examination. By integrating force analysis, it identified a consistent design issue in MacPherson suspension systems, where the shock absorber assembly is subjected to lateral forces. Optimization strategies and bench testing methodologies were proposed to address these issues.

The recommended optimization measures can be implemented in future suspension system development. These solutions provide a systematic approach to reducing coating wear at the spring-seat interface, helping to prevent stress corrosion failure in post-market applications.

No.	Spring Parameters	Wear Test Cycles (Lower End Coil Coating Damage >3mm)	Salt Spray Test	Dry Fatigue Failure Cycles
Original	Hardness: 54–57 HRC	42,375 cycles / 37,658	Rust observed at wear	426,572 cycles /
Design	Coating Thickness: 60–80 µm	cycles	location	430,351 cycles
Solution 1	Hardness: 55.5–56 HRC Coating Thickness: 80–100 µm	46,585 cycles / 47,235 cycles	Rust observed at wear location	514,844 cycles / 516,920 cycles
Solution 2	Hardness: 54–56 HRC Coating Thickness: 60–80 µm	Protective sleeve remained intact after 60,000 cycles	No visible rust	534,256 cycles / 526,920 cycles
Solution 3	Hardness: 54–55 HRC Coating Thickness: 150–200 µm	54,595 cycles / 55,980 cycles	Rust observed at wear location	522,350 cycles / 526,257 cycles

Table 2. Comparison of Test Results for Different Design Solutions

References

- Zhang, Q., Chen, K., Fu, Y., Wang, C., Chen, D., Mei, H., Liu, Z., Dai, Y., & Cong, D. (2021). Study on fracture failure behavior of vehicle suspension coil springs. *Equipment Environmental Engineering*, 18(8), 100-106.
- [2] Wang, J., Xue, S., Sun, X., & Feng, G. (2020). Optimization study on lateral force of MacPherson suspension dampers based on ADAMS. Automotive Practical Technology(11), 70-71, 76.
- [3] Liang, Y. (2010). Application of stress shot peening in post-treatment of coil springs. Shanghai Automobile(2), 40-41.
- [4] Gao, Y., Yue, K., & Yue, Q. (2023). Study on lateral stiffness of cylindrical coil springs based on computed height correction method. National Defense Traffic Engineering and Technology, 21(6), 15-18, 4.
- [5] Dong, Z., Yang, J., Fan, F., & Wang, L. (2024). Study on stress corrosion performance of high-strength alloy steel. *Materials Development and Application*, 39(3), 56-60.
- [6] Chao, Y., Zhi, C., & Cai, J. (2018). Analysis and improvement of fracture issues in automotive coil spring end coils. Automotive Practical Technology(11), 55-57.